




Corrosion



Local corrosion on girder edge



Broken girder edge due to corrosion




Anchor of PC cables inside the girder

Sag at the mid-span hinge position

Sag at the central hinge



Horizontal metal bearing



ゲレンク沓側面図



Built in 1971

$L = 161.65 \text{ m} (33.5 + 72 + 53)$

2002 & 2012 Specifications for Highway Bridges

1. International trend in promoting performance-based codes to ease trade barriers (ISO2394 (1998))
2. Flexible acceptance to innovative technologies in construction projects to meet diversifying technical proposals
3. Needs for durable and maintenance-friendly structures



Advent of Performance-based Specifications

- 1) From prescriptive to performance-based: Required performance criteria were philosophically set out, as requested by ISO2394
- 2) Performances comes first and mandated. Standards are regarded as acceptable solutions. Alternatives can be confirmed to see if the alternatives offer equivalent or greater performances than the standards.
- 3) Prescriptions for durability demands on fatigue in steel members, and chloride ingress in concrete members, durable RC deck slab design etc were shown.
- 4) A maintenance plan and relevant countermeasures are required in initial design.

A big Issue in promoting innovative procurements:

How to evaluate the durability & establish QA/QC processes in construction for new materials and structures



Figure 10. This photograph, taken in the westbound D Street portal tunnel after the accident, shows a number of roof hanger plates that have begun to pull away from the tunnel roof, including the two-anchor hanger plate in the foreground and the four-anchor plate adjacent to it.

I-95 Mianus River Bridge



CONNOR, R.J. et al., Inspection and Management of Bridges with Fracture-Critical Details, NCHRP SYN. 354, 2005



Sudden collapse of de la Concorde Overpass, Quebec, Canada, in 2006

RC drop-in girder, $L = 60.8$ m

Built in 1970 and collapsed in 2006 (36-year old)

Cause: Corrosion of reinforcement bars, inadequate reinforcement arrangement, & insufficient amount of reinforcement, resulting in shear failure of a drop-in span



Ref: "Commission of Inquiry into the Collapse of a Portion of the de la Concorde Overpass"

Collapse of I-70 Bridge, US, in 2005

Post-tension PC bridge,

Length = 26 m

Built in 1950 and suddenly
collapsed in 2005 (55-year old)

Cause: Corrosion and failure in PC
cables



Collapse of Ynys-y-Gwas Bridge, UK, in 1985

Post-tension & segmental girder PC bridge, Length = 18.3 m

Built in 1953 and suddenly collapsed in 1985 (32-year old)

Cause: 1. Corrosion and failure in PC cables


2. Insufficient grouting inside sheaths → Prohibited to construct PC bridges with grouting until 1996

3. De-icing salt in winter



http://www.youtube.com/watch?v=PUg_EqQN6Gg&translated=1

Malfunctioning of two girders in Hoan Bridge (2000.12)



3-span plate girder bridge
with 3 main girders

Fatigue crack starting from
a welding part of gusset to
attach a lateral member



2002 Specifications for Highway Bridges

1. International trend in promoting performance-based codes to ease trade barriers (ISO2394 (1998))
2. Flexible acceptance to innovative technologies in construction projects to meet diversifying technical proposals
3. Needs for durable and maintenance-friendly structures



Advent of Performance-based Specifications

- 1) From prescriptive to performance-based: Required performance criteria were philosophically set out, as requested by ISO2394
- 2) Performances comes first and mandated. Standards are regarded as acceptable solutions. Alternatives can be confirmed to see if the alternatives offer equivalent or greater performances than the standards.
- 3) Prescriptions for durability demands on fatigue in steel members, and chloride ingress in concrete members, durable RC deck slab design etc were shown.
- 4) A maintenance plan and relevant countermeasures are required in initial design.